

DETAILS OF INCIDENT	
Date:	09/12/2016
Time:	0950
Location:	Dubbo Provisioning Centre
Rating:	<input checked="" type="checkbox"/> Low <input type="checkbox"/> Moderate <input type="checkbox"/> Serious
Classification: (e.g. WHS, RCI, etc.)	<input checked="" type="checkbox"/> WHS <input type="checkbox"/> RCI <input type="checkbox"/> Other <u>NMIH417</u> If RCI, what is the TCR: _____/20____
Is the incident reportable to Comcare:	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes, If yes, when was it reported Click here to enter a date.
DESCRIPTION OF INCIDENT (who, what, how, when)	
<p>During the use of a new spitfire pressure cleaner the power point that it was running off shorted out and burnt the 15amp power point and plug. Upon further investigation it was mentioned by one of the ARTC staff that the power point was becoming loose when plugging in appliances.</p> <p>It was suggested by ARTC electrical staff that this may have caused a hot spot in the power point which created a short circuit resulting in the incident.</p>	
DETAILS OF INJURY/ILLNESS/IMPACT/DAMAGE (include photographs and (if possible) an estimate for when track can be released)	
<p>Burnt plug on pressure cleaner</p> 	

Burnt out power point –



IMMEDIATE ACTIONS/CONTROLS TAKEN FOLLOWING INCIDENT TO PREVENT A REPEAT INCIDENT UNTIL INVESTIGATION IS COMPLETE

ARTC electricians isolated the power supply and then replaced power point with new and replaced burnt plug on pressure washer.
 Power point and pressure washer both tested for faults resulting in nil faults found.
 Power points throughout yard will be checked by ARTC electrical staff.

AUTHORISED BY

Name	Simon Benson
Position	Work Group Leader
Shared Learning's	It is suggested that other provisioning centres inspect the condition of all power points prior to use.