

Plant and Equipment - Loading / Unloading

Warning

You cannot undertake this activity in the rail corridor unless you have completed a pre work brief and work site protection plan.

Reference should also be made to the <u>Protocol for Entering the ARTC Rail Corridor</u> and the <u>Business Rules for Working in the ARTC Rail Corridor</u>

Minimum Personal Protective Equipment (PPE) requirements must also be met in line with the <u>Personal Protective Equipment (PPE) Work Instruction</u>.

Work Activity:	Plant and Equipment – Loading / Unloading			WMS No: WHS-WI-002
Coverage:	ARTC employees, and contractors directly managed by ARTC		Version No: 5.0	
Developed by:	Corporate Work Health and Safety Manager	Approved by:	Executive General Manager Enterprise Services	Date Approved: 19 April 2016

What are the tasks involved?	What are the hazards and risks?	What are the control measures?	Related Documents
Arrival at location	Drivers unfamiliar with the site Unsafe delivery / pick up point Uncontrolled vehicle movement Delivery vehicle not stabilised.	Site supervisors or a nominated person must meet delivery drivers to direct them to the delivery or pick up point Ensure the delivery or pick up point is safe (for example, away from power lines, and not on sloping or wet ground where possible) Appoint a vehicle spotter if: - vehicles or plant will operate in close proximity to each other - vehicles may need to move in reverse, and/or - moving vehicles will be in proximity to people Ensure the park brake is applied. Chock delivery vehicle wheels (if necessary) Where required, deploy stabilizers and install outrigger foot plates.	

ARTC

What are the tasks involved?	What are the hazards and risks?	What are the control measures?	Related Documents
Loading / Unloading mobile plant	Unsafe deck and/or ramps Unexpected movements Fall / Roll Over Person hit by mobile plant Loads not properly restrained Person struck by load restraints	Only a competent person may load / unload plant and equipment from a delivery vehicle. Check the safety of the deck and/or ramps - ensure area on which ramp is to be lowered is clear - ensure the ramps are secure - check that surfaces are free of debris - check that there will be enough friction for a controlled move Set up an exclusion zone so that a person may not work or walk in to an area where the operator will not see them. Confirm communication protocols with the operator, including conditions for anyone entering the exclusion zone if required. Appoint a spotter to assist and direct the operator as necessary. Plant with ground engagement tools must have blades or attachments as low as possible. Use to help balance as needed. When loading, ensure materials are properly secured and restrained against uncontrolled movement. When unloading, release tie down ropes / chains in sequence.	Load Restraint Guide (see references below)
Loading / Unloading goods or materials	Manual Handling	Apply controls for manual tasks Know the load length, weight, and balance point before lifting Use mechanical lifting devices where possible	Manual Tasks Work Method Statement Load Restraint Guide (see references below)

ARTC

What are the tasks involved?	What are the hazards and risks?	What are the control measures?	Related Documents
	Exceeding safe working limits	Do not exceed safe working load limit on mechanical lifters	
	Person hit in swing zone	Set up an exclusion zone to keep workers clear of any swing zone.	
	Loads not properly restrained	When loading, ensure materials are properly secured and restrained against uncontrolled movement.	
	Person struck by load restraints	When unloading, release tie down ropes / chains in sequence.	
		If used, stand to one side of not directly behind any leverage bar.	



References	
Standards, Codes of Practice, Guidance:	Plant / Equipment / Tools:
Commonwealth Work Health and Safety Regulation (sections 214, 215, 218, 219, 220)	Plant and Equipment
Load Restraint Guide - National Transport Commission - Guidelines and Performance Standards for the Safe Carriage of Loads on Road Vehicles	Exclusion zone delineation equipment, such as witches hats or warning tape Outrigger foot plates (where required) Load restraints (for example chocks, ratchet straps) Personal Protective Equipment
	 rigger gloves eye protection hard hat Consider additional PPE requirements as appropriate to the work, such as: eye and face protection gloves hard hat
Training Requirements: Check whether high-risk licenses are required and if so that workers have these. (The Commonwealth Work Health and Safety Regulation, Schedule 3, requires high-risk work licences for scaffolding, rigging, boom-type elevating work platform operation and fork lift truck operation). Check that workers have the information, training, instruction or supervision that is necessary to protect them from risks arising from the use of plant.	Inspection / Testing requirements: Tie down straps and chains must be inspected for use before loading Mechanical lifting aids to be marked with approved safe working load (safe work load (SWL) / working load limit (WLL)