


DETAILS OF INCIDENT	
Date:	16/02/2017
Time:	0507
Location:	677.745 km Camurra level crossing
Rating:	<input type="checkbox"/> Low <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Serious
Classification: (e.g. WHS, RCI, etc.)	<input type="checkbox"/> WHS <input checked="" type="checkbox"/> RCI <input type="checkbox"/> Other _____ If RCI, what is the TCR: <u>1893</u> /2017__
Is the incident reportable to Comcare:	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes, If yes, when was it reported <a href="#">Click here to enter a date.</a>
DESCRIPTION OF INCIDENT (who, what, how, when)	
<p>An unknown vehicle collided with the rail lights and bells and guardrail at a level crossing near Moree. The local Police informed Network Control of the incident advising there could be debris on the track. The local team leader was notified and arranged a site inspection.</p> <p>Upon inspection, it was found that there was significant damage to signalling infrastructure. The level crossing has been booked out for repairs.</p>	
DETAILS OF INJURY/ILLNESS/IMPACT/DAMAGE (include photographs and (if possible) an estimate for when track can be released)	
<p>Damaged light and bells standard and base</p> 	



**IMMEDIATE ACTIONS/CONTROLS TAKEN FOLLOWING INCIDENT TO PREVENT A REPEAT INCIDENT UNTIL INVESTIGATION IS COMPLETE**

0920 hours PO C Elfes requested TOA B0415 until 1200 hours 03/03/2017 for signal repairs.

0926 hours Signal maintainer D Mealing booked out Newell Highway Level crossing at 677.745 km for repairs. IBA DM 63.

Damaged assets removed from site.

**AUTHORISED BY**

<b>Name</b>	Wally Walker
<b>Position</b>	Area Manager
<b>Shared Learning's</b>	Always remain alert and pay attention to areas of any recent incident in the event that rail infra-structure has been damaged. This could lead to debris on the track or level crossing equipment failing to operate.