

SAFE Notice 1020 1024

Telegram

SYDNEY 8 APRIL 1100 HOURS

TO:

SYDNEY TRAINS

Deputy Executive Director Network Operations

Head of Service Delivery

Area Operations Managers Signal Box Operations

ROC Sydney

Signal Box Operations

Deputy Executive Directors Train Crew

Crew Managers Train Crew

Shift Managers Train Crew

NSW TRAINS

Associate Director Network Coordination

Principal Manager Centralised Station & Crew Support

Standards Officers Centralised Station & Crew Support

I ABSOLUTE SIGNAL BLOCKING (ASB) UPDATED REQUIREMENTS

From Wednesday 15 April 2020, this Safe Notice Telegram cancels and replaces Safe Notice Telegram 1047 – 2019.

In exception to NWT 308: Absolute Signal Blocking, when blocking facilities have been applied to exclude rail traffic from a portion of line, blocking facilities MUST not be removed to allow signals to be cleared for an alternate route. Blocking facilities MUST remain applied while the ASB is in force.

These requirements will also apply when blocking facilities are applied to signals that are used to exclude rail traffic from a portion of line in accordance with NTR 432: Protecting activities associated with in service rail traffic.

SYDNEY, 8 APRIL 2020

DIRECTOR SAFETY AND STANDARDS SYDNEY TRAINS

Returned to Controlling Manager: Date: Signed:	
(Cut along this line and forward the detached receipt to your Controlling Manager)	-
To Controlling Manager:	
Received SAFE Notice No. 1024 – 2020 Date: Signed:	
Name (print): Location:	
(Controlling Manager to retain this Acknowledgment of Receipt of the SAFE Notice for record purposes for 90 days.)	