

EVENT SUMMARY REPORT

EVENT DETAILS		
Relates To	<input checked="" type="checkbox"/> WHS	<input type="checkbox"/> Environment <input type="checkbox"/> Rail Safety
Type	<input type="checkbox"/> Hazard <input type="checkbox"/> Near Miss <input type="checkbox"/> Improvement	<input checked="" type="checkbox"/> Incident
Date and Time	14/10/2020	Closedown <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Location and Kilometres	Baan Baa 531.120 kilometrage	.


EVENT DESCRIPTION AND ACTIONS TAKEN

Description (include relevant images)

At 1000 hours the designated vegetation contractor for the Gunnedah Provisioning centre proceeded to enter the rail corridor in a light vehicle at Baan Baa 531.120 km for the purpose of conducting inspections. As the Vehicle was proceeding it came to an abrupt halt. The driver immediately secured the vehicle and exited to inspect. The vehicle had struck a piece of Railway line that appeared to be concreted into the ground and being used as a gate stop. The gate was open at the time.




EVENT SUMMARY REPORT

	 <p>Line Name: Main NW Single Line Section: Boggabri to Emerald Hill Kilometerage: 531.12 Date: 13-10-2020 10:04:34</p>	
<p>Immediate Actions/ Controls Taken/ Solutions Identified</p>	<ul style="list-style-type: none"> Reported to Area Manager 	
<p>Fatal and Severe Risk</p>	<p>n/a</p>	
<p>Reported By</p>	<p>Shane O'Donohue</p>	
<p>Team/Project</p>	<p>Gunnedah PC</p>	
<p>Responsible Principal Contractor/Operator</p>	<p>Contractor</p>	<p>Company Name:</p>

EVENT SUMMARY REPORT

CORRECTIVE ACTIONS <i>(do not include immediate actions or controls listed above)</i>			
	Action	By Who	By When
1			02/09/2020

Confirm Notifications Completed (where required)	
Network Control (for TCR)	<input checked="" type="checkbox"/> N/A <input type="checkbox"/> Yes #
Injury (Injury Hotline Ref # / Employer Notification)	<input checked="" type="checkbox"/> N/A <input type="checkbox"/> Yes #
External (eg. Environment, Comcare, ONRSR)	<input checked="" type="checkbox"/> N/A <input type="checkbox"/> Yes #

INITIAL CLASSIFICATION			
Event Severity	Actual	<input type="checkbox"/> Significant (1) <input type="checkbox"/> Major (2) <input type="checkbox"/> Minor (3) <input checked="" type="checkbox"/> Negligible (4)	
	Potential	<input type="checkbox"/> Significant (1) <input type="checkbox"/> Major (2) <input type="checkbox"/> Minor (3) <input checked="" type="checkbox"/> Negligible (4)	
Classification	<input type="checkbox"/> Employee <input checked="" type="checkbox"/> Contractor <input type="checkbox"/> Third Party		
Injury Classification	Select a classification Note: Please record a single classification only. If further information is required to confirm classification, please discuss with your Safety Advisor prior to form submission.		
Environment Category	N/A		
Leader Approval	Shane O'Donohue	Signature	
Team/ Project	Gunnedah PC	Position	Area Manager
Date and Time	14/10/2020		
Is Investigation Commencing	<input type="checkbox"/> Yes <i>(Event Severity Levels 1, 2 and 3 for Incident & Near Miss Only)</i> <i>Note: Level 4 is optional</i>		<input type="checkbox"/> Nil Required <i>(Event Severity Level 4 for Incident, Near Miss and Hazards)</i>

ONCE COMPLETED
Submit Completed Forms, including any attachments (photos, documents) to: (Hunter Level 1/2/3) internalincidentalerts@artc.com.au (Hunter Level 4) hv-sct@artc.com.au (Inland Rail) inlandrailsafetyteam@artc.com.au (safety); IREnvironmentCompliance@artc.com.au (environment) (Interstate) hazard@artc.com.au ; (Other) safetymatters@artc.com.au